Warning Signs - Hazardous Substances

Safety in the workplace is currently receiving more attention than ever before. Dangerous substances are a permanent source of danger - so giving correct and detailed information about the risks involved in using and handling these substances is absolutely vital. It is the only way to prevent employees from becoming victims of occupational injury. Of crucial importance in this matter is the correct labelling of bottles, barrels and other containers of dangerous substances.

Pictogram	Size in mm (H x W)	Selfadhesive Vinyl B-930	Rigid PVC B-7526
Flammable material			
PIC 300	100 x 100	259674	
	200 x 200	259675	259676
	300 x 300	259677	259678
Flammable			
STE 501	200 x 150	259683	259684
	400 x 300	259685	259686
Danger Highly flammable liquid			
STE 502	200 x 150	259691	259692
	400 x 300	259693	259694
Danger Highly flammable store			
STE 503	200 x 150	259699	259700
	400 x 300	259701	259702
Danger Asbestos			
STE 899	200 x 150	258650	258651
	400 x 300	258652	258653

Pictogram	Size in mm (H x W)	Selfadhesive Vinyl B-930	Rigid PVC B-7526
Danger Fire risk			
STE 500	200 x 150	259679	259680
	400 x 300	259681	259682
Danger Highly flammable material			
STE 900	200 x 150	259687	259688
	400 x 300	259689	259690
Danger Highly flammable gases			
STE 902	200 x 150	259695	259696
	400 x 300	259697	259698
Highly flammable L.P.G.			
STE 504	200 x 150	259703	259704
	400 x 300	259705	259706
Liquid nitrogen			
STE 549	200 x 150	258654	258655
	400 x 300	258656	258657