

RKZ-KK Series

Silicon Planar Zener Diode for Surge Absorption and Stabilizer

REJ03G1518-0100 Rev.1.00 Mar 02, 2007


Features

- Emboss Taping Reel Pack.
- Super small Flat Lead Package (SFP) is suitable for surface mount design.

Ordering Information

Part No.	Laser Mark	Package Name	Package Code
RKZ-KK Series	Let to Mark Code	SFP	PUSF0002ZB-A

Pin Arrangement



Absolute Maximum Ratings

 $(Ta = 25^{\circ}C)$

Item	Symbol	Value	Unit
Power dissipation	Pd * ¹	150	mW
Junction temperature	Тј	150	°C
Storage temperature	Tstg	-55 to +150	°C

Note: 1. With P.C. Board.

Electrical Characteristics

								$(Ta = 25^{\circ}C)$
Zener Vol		<u> </u>		Dynamic Resistance		ESD-Capability * ²		
			Test		Test		Test	2
	Vz (V) * ¹	Condition	I _R (μΑ)	Condition	r _d (Ω)	Condition	$-(kV)^{*^2}$
Part No.	Min	Max	I _Z (mA)	Max	V _R (V)	Max	I _z (mA)	Min
RKZ2.0BKK	1.90	2.20	5	120	0.5	100	5	30
RKZ2.2BKK	2.10	2.40	5	120	0.7	100	5	30
RKZ2.4BKK	2.30	2.60	5	120	1.0	100	5	30
RKZ2.7B2KK	2.65	2.90	5	120	1.0	110	5	30
RKZ3.0B2KK	2.95	3.20	5	50	1.0	120	5	30
RKZ3.3B2KK	3.25	3.50	5	20	1.0	130	5	30
RKZ3.6B2KK	3.55	3.80	5	10	1.0	130	5	30
RKZ3.9B2KK	3.87	4.10	5	10	1.0	130	5	30
RKZ4.3B2KK	4.15	4.34	5	10	1.0	130	5	30
RKZ4.7B2KK	4.55	4.75	5	10	1.0	130	5	30
RKZ5.1B2KK	4.98	5.20	5	5	1.5	130	5	30
RKZ5.6B2KK	5.49	5.73	5	5	2.5	80	5	30
RKZ6.2B2KK	6.06	6.33	5	2	3.0	50	5	30
RKZ6.8B2KK	6.65	6.93	5	2	3.5	30	5	30
RKZ7.5B2KK	7.28	7.60	5	2	4.0	30	5	30
RKZ8.2B2KK	8.02	8.36	5	2	5.0	30	5	30
RKZ9.1B2KK	8.85	9.23	5	2	6.0	30	5	30
RKZ10B2KK	9.77	10.21	5	2	7.0	30	5	30
RKZ11B2KK	10.76	11.22	5	2	8.0	30	5	30
RKZ12B2KK	11.74	12.24	5	2	9.0	35	5	30
RKZ13B2KK	12.91	13.49	5	2	10.0	35	5	30
RKZ15B2KK	14.34	14.98	5	2	11.0	40	5	25
RKZ16B2KK	15.85	16.51	5	2	12.0	40	5	25
RKZ18B2KK	17.56	18.35	5	2	13.0	45	5	25
RKZ20B2KK	19.52	20.39	5	2	15.0	50	5	20
RKZ22B2KK	21.54	22.47	5	2	17.0	55	5	20
RKZ24B2KK	23.72	24.78	5	2	19.0	60	5	15
RKZ27BKK	25.10	28.90	2	2	21.0	70	2	15
RKZ30BKK	28.00	32.00	2	2	23.0	80	2	13
RKZ33BKK	31.00	35.00	2	2	25.0	80	2	8
RKZ36BKK	34.00	38.00	2	2	27.0	90	2	8

Notes: 1. Tested with pulse (Pw = 40 ms).

2. C =150 pF, R = 330 Ω , Both forward and reverse direction 10 pulse Failure criterion ; According to IR spec

3. The material of lead is exposed for cutting plane. Therefore, soldering nature of lead tip part is considered as unquestioned. Please kindly consider soldering nature.

RENESAS

Mark Code


Part No.	Mark No.	Part No.	Mark No.
RKZ2.0BKK	C1	RKZ9.1B2KK	G3
RKZ2.2BKK	C2	RKZ10B2KK	G6
RKZ2.4BKK	C3	RKZ11B2KK	G9
RKZ2.7B2KK	C5	RKZ12B2KK	J3
RKZ3.0B2KK	C7	RKZ13B2KK	J6
RKZ3.3B2KK	C9	RKZ15B2KK	J9
RKZ3.6B2KK	D2	RKZ16B2KK	M3
RKZ3.9B2KK	D4	RKZ18B2KK	M6
RKZ4.3B2KK	D6	RKZ20B2KK	M9
RKZ4.7B2KK	D9	RKZ22B2KK	P3
RKZ5.1B2KK	E3	RKZ24B2KK	P6
RKZ5.6B2KK	E6	RKZ27BKK	P8
RKZ6.2B2KK	E9	RKZ30BKK	P9
RKZ6.8B2KK	F3	RKZ33BKK	N4
RKZ7.5B2KK	F6	RKZ36BKK	N5
RKZ8.2B2KK	F9		

Note: 1. Example of Marking

C1 🗍 RKZ2.0BKK


RKZ36BKK

Main Characteristic



RENESAS

Package Dimensions



RenesasTechnology Corp. Sales Strategic Planning Div. Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan



RENESAS SALES OFFICES

Refer to "http://www.renesas.com/en/network" for the latest and detailed information.

Renesas Technology America, Inc. 450 Holger Way, San Jose, CA 95134-1368, U.S.A Tel: <1> (408) 382-7500, Fax: <1> (408) 382-7501

Renesas Technology Europe Limited Dukes Meadow, Millboard Road, Bourne End, Buckinghamshire, SL8 5FH, U.K. Tel: <44> (1628) 585-100, Fax: <44> (1628) 585-900

Renesas Technology (Shanghai) Co., Ltd. Unit 204, 205, AZIACenter, No.1233 Lujiazui Ring Rd, Pudong District, Shanghai, China 200120 Tel: <86> (21) 5877-1818, Fax: <86> (21) 6887-7898

Renesas Technology Hong Kong Ltd. 7th Floor, North Tower, World Finance Centre, Harbour City, 1 Canton Road, Tsimshatsui, Kowloon, Hong Kong Tel: <852> 2265-6688, Fax: <852> 2730-6071

Renesas Technology Taiwan Co., Ltd. 10th Floor, No.99, Fushing North Road, Taipei, Taiwan Tel: <886> (2) 2715-2888, Fax: <886> (2) 2713-2999

Renesas Technology Singapore Pte. Ltd. 1 Harbour Front Avenue, #06-10, Keppel Bay Tower, Singapore 098632 Tel: <65> 6213-0200, Fax: <65> 6278-8001

Renesas Technology Korea Co., Ltd. Kukje Center Bldg. 18th Fl., 191, 2-ka, Hangang-ro, Yongsan-ku, Seoul 140-702, Korea Tel: <82> (2) 796-3115, Fax: <82> (2) 796-2145

Renesas Technology Malaysia Sdn. Bhd Unit 906, Block B, Menara Amcorp, Amcorp Trade Centre, No.18, Jalan Persiaran Barat, 46050 Petaling Jaya, Selangor Darul Ehsan, Malaysia Tel: <603> 7955-9390, Fax: <603> 7955-9510

http://www.renesas.com