

For price information, refer to the enclosed price list


Mandatory Signs

| Pictogram | Size in mm (H x W) | Selfadhesive Vinyl B-930 | Rigid PVC B-7526 |
|-----------|--------------------|--------------------------|------------------|
|-----------|--------------------|--------------------------|------------------|

| Pictogram | Size in mm (H x W) | Selfadhesive Vinyl B-930 | Rigid PVC B-7526 |
|-----------|--------------------|--------------------------|------------------|
|-----------|--------------------|--------------------------|------------------|


Wear gloves

| | | | |
|---------|-----------|--------|--------|
| STE 854 | 200 x 150 | 259360 | 259361 |
| | 400 x 300 | 259362 | 259363 |




Hand protection must be worn

| | | | |
|---------|-----------|--------|--------|
| STE 308 | 200 x 150 | 259364 | 259365 |
| | 400 x 300 | 259366 | 259367 |




Hands must be washed

| | | | |
|---------|-----------|--------|--------|
| PIC 271 | 100 x 100 | 259368 | |
| | 200 x 200 | 259369 | 259370 |
| | 300 x 300 | 259371 | 259372 |




Now wash your hands please

| | | | |
|---------|-----------|--------|--------|
| STE 852 | 200 x 150 | 259373 | 259374 |
| | 400 x 300 | 259375 | 259376 |




Respiratory equipment must be worn

| | | | |
|---------|-----------|--------|--------|
| PIC 253 | 100 x 100 | 259377 | |
| | 200 x 200 | 259378 | 259379 |
| | 300 x 300 | 259380 | 259381 |




Respirators must be worn in this area

| | | | |
|---------|-----------|--------|--------|
| STE 309 | 200 x 150 | 259382 | 259383 |
| | 400 x 300 | 259384 | 259385 |




Wear mask

| | | | |
|---------|-----------|--------|--------|
| STE 850 | 200 x 150 | 259386 | 259387 |
| | 400 x 300 | 259388 | 259389 |




Wear welding mask

| | | | |
|---------|-----------|--------|--------|
| STE 310 | 200 x 150 | 259390 | 259391 |
| | 400 x 300 | 259392 | 259393 |




Wear protective clothing

| | | | |
|---------|-----------|--------|--------|
| STE 849 | 200 x 150 | 259394 | 259395 |
| | 400 x 300 | 259396 | 259397 |




Lab coats must be worn in this area

| | | | |
|---------|-----------|--------|--------|
| STE 311 | 200 x 150 | 259398 | 259399 |
| | 400 x 300 | 259400 | 259401 |




Protective clothing must be worn in this area

| | | | |
|---------|-----------|--------|--------|
| STE 312 | 200 x 150 | 259402 | 259403 |
| | 400 x 300 | 259404 | 259405 |



Lifejackets must be worn

| | | | |
|---------|-----------|--------|--------|
| STE 313 | 200 x 150 | 259406 | 259407 |
| | 400 x 300 | 259408 | 259409 |



High visibility clothing must be worn in this area

| | | | |
|---------|-----------|--------|--------|
| STE 314 | 200 x 150 | 259410 | 259411 |
| | 400 x 300 | 259412 | 259413 |

