



Basic Part No. \_\_\_\_\_ **600-076**

Basic Part No. \_\_\_\_\_ **600-004**




**600-076 High Torque**

Hand-Held Torque Wrenches 3/8" Drive.  
Requires two Panasonic SR44W or  
equivalent batteries.  
600-076 High Torque (adjustable to  
desired torque level of 20 to 360 inch lbs.)



**600-004 Standard Torque**

Hand-Held Torque Wrenches 3/8" Drive.  
Requires two Panasonic SR44W or  
equivalent batteries.  
600-004 Standard Torque (adjustable to  
desired torque level 0 - 150 inch lbs.)



Bench mounted units as well as connector plug and receptacle holders (sockets) are available for all popular connector types. Please see the Glenair *Backshell Assembly Tools Banding Tools and Accessory Tools* catalog for ordering information.